**Zirconium & Zirconium Alloy Scrap:** Borings, Clippings, Shavings, Turnings and Scalpings, Fines (wet)

UN1358 SDS: SAC011

22-Nov-2019 Ver 5

**Zirconium & Zirconium Alloy Scrap:** Borings, Clippings, Shavings, **Turnings and Scalpings, Fines (wet)** 

**DANGER** 

Flammable solids

UN1358 SDS: SAC011

22-Nov-2019 Ver 5

## **DANGER**

Flammable solids



Wear protective gloves/protective clothing/eve protection. Keep away from heat/sparks/open flames/hot surfaces. - No smoking. Ground/bond container and receiving equipment. If dust clouds can occur, use explosion-proof electrical/ ventilating/lighting/equipment.

In case of fire: Use salt (NaCl) or class D dry powder for extinction.

Wear protective gloves/protective clothing/eve protection. Keep away from heat/sparks/open flames/hot surfaces. - No smoking. Ground/bond container and receiving equipment. If dust clouds can occur, use explosion-proof electrical/ ventilating/lighting/equipment.

In case of fire: Use salt (NaCl) or class D dry powder for extinction.



ATI. 1000 Six PPG Place Pittsburgh, PA 15222 USA CHEMTREC: +1703-741-5970

Safety data sheets and labels available at ATImetals.com



ATI. 1000 Six PPG Place Pittsburgh, PA 15222 USA

Safety data sheets and labels available at ATImetals.com

**Zirconium & Zirconium Alloy Scrap:** Borings, Clippings, Shavings, **Turnings and Scalpings, Fines (wet)** 

**UN1358** SDS: SAC011

22-Nov-2019 Ver 5

**Zirconium & Zirconium Alloy Scrap:** Borings, Clippings, Shavings, **Turnings and Scalpings, Fines (wet)** 

UN1358 SDS: SAC011

22-Nov-2019 Ver 5

CHEMTREC: +1703-741-5970

CHEMTREC: +1703-741-5970

## **DANGER**

Flammable solids



Wear protective gloves/protective clothing/eye protection. Keep away from heat/sparks/open flames/hot surfaces. - No smoking. Ground/bond container and receiving equipment. If dust clouds can occur, use explosion-proof electrical/ ventilating/lighting/equipment.

In case of fire: Use salt (NaCl) or class D dry powder for extinction.

## **DANGER**

Flammable solids



Wear protective gloves/protective clothing/eye protection. Keep away from heat/sparks/open flames/hot surfaces. - No smoking. Ground/bond container and receiving equipment.

If dust clouds can occur, use explosion-proof electrical/ ventilating/lighting/equipment.

In case of fire: Use salt (NaCl) or class D dry powder for extinction.



ATI, 1000 Six PPG Place Pittsburgh, PA 15222 USA CHEMTREC: +1703-741-5970

ATI. 1000 Six PPG Place Pittsburgh, PA 15222 USA

Safety data sheets and labels available at ATImetals.com

afety data sheets and labels available at ATImetals.com