Zirconium Sponge (distilled)

UN3089 SDS: SAC002

DANGER

Flammable solid



Wear protective gloves/protective clothing/eye protection.
Keep away from heat/sparks/open flames/hot surfaces. - No smoking.
Ground/bond container and receiving equipment.
If dust clouds can occur, use explosion-proof
electrical/ventilating/lighting/equipment.
In case of fire: Use salt (NaCl) or class D dry powder for extinction.



ATI Specialty Alloys & Components CHEMTREC: +1 800-424-9300 1600 Old Salem NE, Albany OR 97321 USA

Safety data sheets and labels available at ATImaterials.com

Zirconium Sponge (distilled)

UN3089 SDS: SAC002 13-Jan-2025 Ver 7 NA-EN

DANGER

Flammable solid



Wear protective gloves/protective clothing/eye protection.
Keep away from heat/sparks/open flames/hot surfaces. - No smoking.
Ground/bond container and receiving equipment.
If dust clouds can occur, use explosion-proof
electrical/ventilating/lighting/equipment.
In case of fire: Use salt (NaCl) or class D dry powder for extinction.



ATI Specialty Alloys & Components CHEMTREC: +1 800-424-9300 1600 Old Salem NE, Albany OR 97321 USA

Safety data sheets and labels available at ATImaterials.com

Zirconium Sponge (distilled)

UN3089 SDS: SAC002

DANGER

Flammable solid



Wear protective gloves/protective clothing/eye protection.
Keep away from heat/sparks/open flames/hot surfaces. - No smoking.
Ground/bond container and receiving equipment.
If dust clouds can occur, use explosion-proof
electrical/ventilating/lighting/equipment.
In case of fire: Use salt (NaCl) or class D dry powder for extinction.

Zirconium Sponge (distilled)

UN3089 SDS: SAC002

DANGER

Flammable solid



Wear protective gloves/protective clothing/eye protection.
Keep away from heat/sparks/open flames/hot surfaces. - No smoking.
Ground/bond container and receiving equipment.
If dust clouds can occur, use explosion-proof electrical/ventilating/lighting/equipment.
In case of fire: Use salt (NaCl) or class D dry powder for extinction.



ATI Specialty Alloys & Components CHEMTREC: +1 800-424-9300 1600 Old Salem NE, Albany OR 97321 USA

Safety data sheets and labels available at ATImaterials.com

Zirconium Sponge (distilled)

UN3089 SDS: SAC002

DANGER

Flammable solid



Wear protective gloves/protective clothing/eye protection.
Keep away from heat/sparks/open flames/hot surfaces. - No smoking.
Ground/bond container and receiving equipment.
If dust clouds can occur, use explosion-proof
electrical/ventilating/lighting/equipment.
In case of fire: Use salt (NaCl) or class D dry powder for extinction.



ATI Specialty Alloys & Components CHEMTREC: +1 800-424-9300 1600 Old Salem NE, Albany OR 97321 USA

Safety data sheets and labels available at ATImaterials.com

Zirconium Sponge (distilled)

UN3089 SDS: SAC002

DANGER

Flammable solid



Wear protective gloves/protective clothing/eye protection.
Keep away from heat/sparks/open flames/hot surfaces. - No smoking.
Ground/bond container and receiving equipment.
If dust clouds can occur, use explosion-proof
electrical/ventilating/lighting/equipment.
In case of fire: Use salt (NaCl) or class D dry powder for extinction.

ATI Specialty Alloys & Components CHEMTREC: +1 800-424-9300 1600 Old Salem NE, Albany OR 97321 USA

Safety data sheets and labels available at ATImaterials.com

ATI Specialty Alloys & Components CHEMTREC: +1 800-424-9300 1600 Old Salem NE, Albany OR 97321 USA

Safety data sheets and labels available at ATImaterials.com